50

40

30

20

10

5

Step 0: Check and/or calibrate your printing formes. For lithographic offset plates you can first produce only the black plate and use **PLATE** software:

0 % 10 % 20 % 30 % 40 % 50 % 60 % 70 % 80 % 90 % 100 %

Geometrical 50% if plate is calibrated and no gravure curve is used

Check your 50% geometrical dot area with a magnifier or measure your offset plates model N-Factor:

40% 70%